

Queue Number 2870338

Transaction Date 16 Oct 2026, 12:27:02

Site Name
840 - Emirates AuctionsTransaction Number
12669041 (CC10009) (CC10012)

Vehicle Details

Chassis Number	5GRGN23U13*****
Specification	Imported
Make	Hummer
Model	H2
Model Year	2003
Color	Unknown
Mileage	175537 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REFITTED	أبواب
01.D Floor	FLOOR CHASSIS SUSPENSION THICK RUST PROOFED	الارضية
01.E Windshield	FRONT SPOT CRACK	زجاج
01.F Roof	REPAIRED	السقف
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	NOT OPEN , HANDLE LOOSE	صندوق
01.I Door Handle & Lock	SWITCH LOCK NOT WORKING	مقابض الأبواب والأقفال
01.J Vehicle Color	GREEN	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION DENT , COPELTLY THICK RUST PROOFED, PORTION RUSTY	الشاسيه
02.B Chassis Number	STICKER PORTION FADED , CONSOLE BOX NUMBER NOT MATCHING WITH OTHERS	رقم القاعدة

03 Engine Condition

المحرك

03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY, SHAKING	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL WET REFITTED ,HOLE COVER MISSING, JERKING DELAY SHIFTING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE NOT WORKING	الاضاءة الرئيسية
07.B Other	LEVER NOT WORKING PROPERLY	اخرى
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.D Fog light	NOT WORKING	كشاف الضباب
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS RUSTY , INTERIOR REFITTED, ELECTRIC FUALT	اخرى
08.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING	المرايا
08.C AC Condition	NOT COOLING , DISPLAY NOT WORKING PROPERLY & SWITCH ADJUSTMENT NOT WORKING	المكيف
08.D Roof Light	NOT WORKING	أنارة السقف
08.E Power Window Switch And Glass	FRONT BOTH SIDE , REAR RIGHT SIDE NOT WORKING , FRONT RIGHT SIDE SWITCH MISSING	مفتاح النافذه و الزجاج
08.F Floor Matting	PORTION LOOSE	فرش الأرضية
08.G Audio	NOT WORKING , BUTTON FADED	صوتيات
08.H Dash Board	PORTION DAMAGED	لوحة القيادة
08.I Roof Ceiling	REPLACED	بطانه السقف
08.J Sun Visor	PORTION LOOSE	حاجب الشمس
08.K Odometer reading	DISPLAY NOT WORKING PROPERLY	قراءة عداد المسافات
08.L Door Panel	PORTION LOOSE	لوحة بطانة الباب
08.M Air Bag	MISSING	وسائد هوائية
08.N Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.O Gear Shifting Lever	SIDE COVER & SHIFTING LOCK DAMAGED	ذراع نقل السرعات
09 Battery Condition		حالة البطارية
09.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae