



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 09 Sep 2021, 18:19:41 |
| Transaction Number | 70174495 (CC10006) | Queue Number | 312309 |



| | |
|----------------|--------------------------|
| Chassis Number | JN8FY15Y89X572868 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Nissan |
| Model | Patrol |
| Model Year | 2009 |
| Color | White |
| Mileage | 0 |

| DEFECT | REMARKS | |
|------------------------------------|---|--------------------|
| 01 Body | | جسم المركبة |
| 01.A Fenders | FRONT LEFT SIDE SLIGHTLY REPAIRED | مدكار |
| 01.B Paint | DENTS & SCRATCHES ON BODY | الصبغ |
| 01.C Rusty | UNDER BODY PARTS , CHASSIS GETTING RUSTY | صدأ |
| 01.D Floor | UNDER FLOOR RUST PROOFED | الارضية |
| 01.E Bumper | SUB MODIFIED | دعامية |
| 01.F Roof | TOP ROOF SLIGHTLY REPAIRED & GETTING RUSTY | السقف |
| 02 Chassis Condition | | الشاسي |
| 02.A Chassis Extension | REAR BOTH SIDE REPAIRED & INNER DENT | تمديدات الشاسي |
| 02.B Chassis | FRONT LEFT SIDE WELDED REPAIRED & CHASSIS FRAME COMPLETELY RUST PROOFED | الشاسيه |
| 03 Seats Condition | | المقاعد |
| 03.A Other | OK | اخرى |
| 04 Wipers and Arms | | المساحات |
| 04.A Other | WORN OUT | اخرى |
| 05 Exhaust System | | نظام العادم |
| 05.A Modification | MODIFIED & NOISY | تعديلات |
| 05.B Other | WELDED & REPAIRED | اخرى |
| 06 Tires and Rims Condition | | الاطارات |

| DEFECT | REMARKS | |
|------------------------------|---|-------------------------|
| 06.A Front Tyre | BOTH SIDE 2020 | الاطار الامامي |
| 06.B Rear Tyre | BOTH SIDE 2020 | الاطار الخلفي |
| 07 Lights | | الاضاءة |
| 07.A Head Light | OK | الاضاءة الرئيسية |
| 07.B Other | OK | اخرى |
| 08 Brake Condition | | الفرامل |
| 08.A Caliber Brake | GETTING RUSTY | جهاز الفرامل |
| 09 Suspension System | | ممتص الصدمات |
| 09.A Arms | FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED | ازرع |
| 09.B Shock Absorber | WEAK & LEAK | ممتص الصدمات |
| 10 Interior Condition | | الاجزاء الداخلية |
| 10.A Other | OK | اخرى |
| 10.B Mirror | OK | المرآيا |
| 10.C AC Condition | OK | المكيف |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

| | |
|----------------------------|---------------------------------------|
| Plate Details : | J 55560 Dubai Private |
| Chassis No : | JN8FY15Y89X572868 |
| Vehicle Make : | NISSAN |
| Vehicle Model : | PATROL |
| Vehicle Class : | Light Vehicle |
| Body Type : | STATION |
| Fuel : | Benzene |
| Color : | White |
| Drive Direction : | Left Hand Side |
| Dimensions : (H x W x L) : | -- x -- x -- |
| Current Odometer : | 258182 Kms. |
| Origin : | Japan |
| Model Year : | 2009 |
| Gear Type : | Automatic |
| Engine Size : | 4800 CC |
| Engine No : | TB48 056890 |
| Horse Power : | -- |
| Axles No : | 2 |
| Cylinders : | 6 |
| No Of Doors : | 4 |
| No Of Seats : | 7 |
| G. V. W. : | Empty Weight : 1950 Kgs. 2550 Kgs. |

| | |
|---------------------------|---------------------|
| Certificate Number : | 5-TAS-2021-15058375 |
| Inspection Date : | 20-09-2021 |
| Certificate Print Date : | 20-09-2021 |
| Services : | Registration Test |
| Vehicle Testing Partner : | Tasjeel |
| Vehicle Testing Center : | Tasjeel Al Aweer |
| Total Time Taken : | 8 min 57 sec |
| Appointment Ref Number : | -- |
| Start Time : | 15:43 |
| End Time : | 15:52 |
| Lane : | 03 |
| Token No. : | 177 |
| Attempt : | 1 |
| Prints No : | 1 |

Carbon footprint



Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate last 12 Months)

| | | | |
|-------------------|------------------------|--------------------|---------------------------|
| | | | |
| 19133 KM | 1969 L | 3190 AED | 4.8 ton |
| Distance per year | Fuel consumed per year | Fuel cost per year | Carbon footprint per year |

Parameter Readings

| | | | |
|---------------------------------------|--------------------------------------|---|------------------------------|
| Service brake imbalance on front axle | Service brake imbalance on rear axle | Parking brake imbalance between LHS and RHS | Vehicle on Petrol CO Reading |
| 1 % | 20 % | 22 % | 0.04 % |

Vehicle on Petrol HC

Reading
12 PPM VOL

Inspection Remarks:

REAR LEFT SHOCK MINOR OIL LEAK/FRONT LEFT SIDE FENDER AND ROOF REPAIRED // BOTH SIDE CHASSIS HEATED & REPAIRED CCM PASSED WORK ORDER # 20210531-005

Payment Details

| | | | |
|-------------------------|--------------------|--------------------|---------------------------------|
| Inspection Performed by | Payment Method | Transaction Number | Service Fees |
| 33706 | VTP Credit Account | 15058375 | AED 170 Collected on 20/09/2021 |
| Parking Slot No | Service Name | Attempt | Received by |
| -- | Registration Test | 1 | Bajurdeen Abdul Gafoor |

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

