

Queue Number 2899051

Transaction Date 22 Oct 2026, 16:50:40

Site Name
840 - Emirates AuctionsTransaction Number
59102626 (CC10013) (CC10019)

Vehicle Details

Chassis Number	WDDWF8HB5F*****
Specification	GCC Specification
Make	Mercedes
Model	C 63 AMG
Model Year	2015
Color	Silver
Mileage	97215 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES,PORTION STICKER	الصبغ
01.C Doors	FRONT BOTH SIDE REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COMPLETELY COVERED	الارضية
01.F Bumper	MISALIGN,SCRATCHES	دعامية
01.G Roof	PORTION STICKER	السقف
01.H Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.I Trunk	PORTION REPAINTED PORTION REPAIRED	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME RADIATOR SUPPORT BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.K Vehicle Color	GRAY	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	اخرى

03 Engine Condition

المحرك

03.A Other	ACCELERATOR NOT WORKING PROPERLY	اخرى
------------	----------------------------------	------

Condition	Remarks	الحالة
03.B Engine Visual Condition	REFITTED , PARTS MODIFIED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Exhaust System		نظام العادم
04.A Modification	EXHAUST SYSTEM MODIFIED	تعديلات
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES & HUB COVER MISSING	حالة الجنوط
06.D Spare Tire &Tools	EXTAR SPACER	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	MINOR LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
09 Interior Condition		الحالة الداخليه
09.A Other	CENTER CONSOLE BOX COVER MINOR WORN OUT / INTERIOR PARTS MINOR GETTING RUSTY	اخرى
09.B AC Condition	OK	المكيف
09.C Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.D Steering Wheel and control buttons	WORN OUT & SWITCH PORTION FADED	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

