



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **08 May 2022, 17:24:02**
 Transaction Number **47010470 (CC10006)** Queue Number **312309**



Chassis Number **WAUS2CFC1EN003860**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Audi**
 Model **S7**
 Model Year **2014**
 Color **White**
 Mileage **139754 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Engine Condition المحرك		
01.A Visual Engine Condition	HAVE SIGN OF MINOR OIL LEAK	حالة المحرك النظري
02 Transmission Condition الجير		
02.A Visual Gear Box Condition	OK	حالة الجير النظري
02.B Road Test	NOT CHECK	فحص علي الطريق
03 Body جسم المركبة		
03.A Floor	UNDER FLOOR FULLY COVERED , CHECKED VISIBLE AREA OK	الارضية
03.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
04 Tires and Rims Condition الاطارات		
04.A Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2018	الاطار الامامي
05 Chassis Condition الشاسي		
05.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

DEFECT	REMARKS	
06 Interior Condition		الحاله الداخليه
06.A AC Condition	OK	المكيف
06.B Power Window Switch	REAR BOTH SIDE NOT WORKING PROPERLY	مفتاح النافذه
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Exhaust System		نظام العادم
08.A Other	PIPE HAVE HOLES	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.