



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 23 Jan 2023, 15:52:32 |
| Transaction Number | 18430835 (CC10010) | Queue Number | 657854 |



| | |
|------------------|--------------------------|
| Chassis Number | WVWMD11K99W107067 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Volkswagen |
| Model | Golf |
| Model Year | 2009 |
| Color | Grey |
| Mileage | 001 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 4 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|--|------------------------|
| 01 Tires and Rims Condition | | الاطارات |
| 01.A Rims Condition | RIMS MINOR DENT ,SCRATCHES | حالة الجنوط |
| 01.B Rear Tyre | LEFT SIDE 2019 CRACKED & RIGHT SIDE 2017 CRACKED,EXPIRED | الاطار الخلفي |
| 01.C Front Tyre | LEFT SIDE 2019 CRACKED & RIGHT SIDE EXPIRED,DAMAGED | الاطار الامامي |
| 02 Suspension System | | ممتص الصدمات |
| 02.A Ball Joint | BOOT CUT | مفصل كروي |
| 02.B Arms | LOWER ARM BUSH CUT | ازرع |
| 02.C Other | STABILIZER LINK BOOT CUT | اخرى |
| 03 Interior Condition | | الحاله الداخليه |
| 03.A Other | GEAR LEVER DUST COVER LOOSE | اخرى |
| 03.B Sunroof | CURTAIN DAMAGED | فتحت سقف |
| 03.C AC Condition | NOT CHECK,GRILL COVER PORTION CRACKED | المكيف |
| 03.D Odometer reading | NOT CHECK | قراءة عداد المسافات |
| 03.E Door Panel | PORTION DAMAGED | لوحة بطانة الباب |
| 03.F Dash Board | PORTION CRACKED | لوحة القيادة |

| DEFECT | REMARKS | |
|---|--|----------------------------|
| 03.G Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 03.H Mirror | LEFT SIDE GLASS DAMAGED | المرابا |
| 04 Chassis Condition | | الشاصي |
| 04.A Chassis | OK | الشاسيه |
| 05 Engine Condition | | المحرك |
| 05.A Visual Engine Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING | حالة المحرك النظرى |
| 06 Transmission Condition | | الجير |
| 06.A Road Test | NOT CHECK | فحص علي الطريق |
| 06.B Visual Gear Box Condition | NOT CHECK | حالة الجير النظرى |
| 07 Body | | جسم المركبة |
| 07.A Floor | UNDER FLOOR COVERED, CHECKED ONLY VISIBLE AREA,COVER PORTION DAMAGED | الارضية |
| 07.B Paint | BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES PORTION FADED,PORTION RUSTY | الصبغ |
| 07.C Bumper | MISALIGN,FRONT DAMAGED | دعامية |
| 07.D Rusty | UNDER BODY PARTS SUSPENSION GETTING RUSTY | صدأ |
| 07.E Fenders | FRONT REFITTED | مدكار |
| 07.F Bonnet | REFITTED,LOCK HANDLE DAMAGED | غطاء المحرك |
| 07.G Doors | FRONT RIGHT SIDE & REAR BOTH SIDE NOT OPEN | أبواب |
| 08 Lights | | الاضاءة |
| 08.A Head Light | LENS FADED,ALL LIGHT NOT CHECK | الاضاءة الرئيسية |
| 09 Seats Condition | | المقاعد |
| 09.A Seat Condition | EXTRA COVER | حالة المقاعد |
| 10 Steering Condition | | المقود |
| 10.A Tie Rod End | BOOT CUT | مؤخرة الرودات |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.