CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899778
Transaction Date	23 Oct 2026, 14:39:33
Site Name	840 - Emirates Auctions
Transaction Number	99969024 (CC10026) (CC10026)



Vehicle Details

Chassis Number	SALVP2BG2H*******
Specification	Imported
Make	Land Rover
Model	Range Rover Evoque
Model Year	2017
Color	Green
Mileage	98356 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED , FRONT BOTH SIDE FIBER PAINT NO CHECK,FRONT LEFT SIDE OUTER SKIRT DAMAGE	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.C Doors	RIGHT SIDE BOTH PORTION REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY , SIGN OF FLOODED	صدأ
01.E Floor	UNDER FLOOR THICK RUST PROOFED PORTION DENTS, MUDDY	الارضية
01.F Bumper	MISALIGN PORTION DAMAGE	دعامية
01.G Trunk	FIBER PAINT NO CHECK	صندوق
01.H Vehicle Color	SILVER / BLACK	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED , CHECK VISIBLE AREA / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY , ABNORMAL SOUND , SIGN OF OIL WET	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Belt	FRONT RIGHT SIDE CUT	حزام الأمان
04.B Seat Condition	PORTION CRACK	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	FRONT BOTH SIDE CRACK , WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	GETTING FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING MESSAGE DISPLAY	ضوء تحذير
08 Brake Condition		**الفرامل**
08.A Brake Pedal	SPONGY	دواسة الفرامل
08.B Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Interior Condition		**الحاله الداخليه**
09.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT	اخري
09.B AC Condition	OK	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القياده
09.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
10 Engine Cooling System		**نظام تبريد المحرك**
10.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae