

#### **TEST CERTIFICATE**

Site Number
Transaction Number

**06 Engine Condition** 

840-Emirates Auctions 34138779 (CC10008) Transaction Date

31 May 2022, 16:08:34

Queue Number 312309

Chassis Number

MHFBU8FS6L0035574

Engine Number

Vehicle Class

Manufacturer **Toyota** 

Model

Fortuner

Model Year

2020

Car

Color

\_\_\_\_

COIOI

White

Mileage

51239 Km

Fuel Type

Petrol

No. Of Cylinders

4

Specification

**GCC** Specification

المحرك

DEFECT REMARKS

01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box	ОК	حالة الجير النظرى
Condition		

#### O2 Interior Condition

### الاطارات 03 Tires and Rims Condition

03.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفى

## O4 Body جسم المركبة

04.A Floor	UNDER BODY & CHASSIS THICK RUST PROOFED	الارضية
04.B Paint	MINOR SCRATCHES	الصبغ

## الشاصي 05 Chassis Condition

US.A Chassis	OK	الشاسيه

# O6.A Visual Engine Condition OK حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا
   تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من