CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2949908
Transaction Date	06 Nov 2026, 09:47:17
Site Name	840 - Emirates Auctions
Transaction Number	76007585 (CC10008) (CC10011)



Vehicle Details

Chassis Number	2G6185S83E*******
Specification	GCC Specification
Make	Cadillac
Model	XTS
Model Year	2014
Color	Blue
Mileage	169534 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	LEFT SIDE BOTH REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION GETTING FADED	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Trunk	PORTION REPAIRED REPAINTED,INNER COVER PORTION LOOSE	صندوق
01.H Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA /OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK ,JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED CRACK	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	REAR RIGHT SIDE MINOR OIL LEAK	ممتص الصدمات
09 Steering Condition		المقود
09.A Axle	REAR RIGHT SIDE OUTER BOOT CUT	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER GETTING WORN OUT	اخري
10.B Mirror	LEFT SIDE FADED,ADJUSTMENT NOT WORKING	المرايا
10.C AC Condition	OK,SWITCH PANEL PORTION CRACK	المكيف
10.D Power Window Switch And Glass	REAR BOTH SIDE CURTAIN HANDLE DAMAGED,FRONT LEFT SIDE SWITCH WORN OUT	مفتاح النافذه و الزجاج
10.E Dash Board	LEATHER PORTION LOOSE WORN OUT	لوحة القياده
10.F Door Panel	PORTION LOOSE WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae