

Queue Number	2792898	Transaction Date	24 Sep 2026, 11:01:15
Site Name	840 - Emirates Auctions	Transaction Number	10724798 (CC10010) (CC10011)



Vehicle Details

Chassis Number	1N4AA6APXM*****
Specification	GCC Specification
Make	Nissan
Model	Maxima
Model Year	2021
Color	Unknown
Mileage	57043 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS COMPLETE THICK RUSTPROOFED.	صدأ
01.D Floor	UNDER FLOOR PORTION MINOR DENT .	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	MISALIGN	غطاء المحرك
01.G Vehicle Color	GRAY.	لون المركبة
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COMPLETE COVERED ,PORTION RUSTPROOFED ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	VISUAL CHECK OK.	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	VISUAL CHECK OK.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2020 CRACK EXPIRED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020 CRACK EXPIRED	الاطار الخلفي
06 Interior Condition		الحالة الداخلية
06.A AC Condition	OK	المكيف
06.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
06.C Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات
07 Battery Condition		حالة البطارية
07.A Battery Condition	WEAK.	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae