



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 May 2023, 12:55:14
Transaction Number	86320219 (CC10010)	Queue Number	716248



Chassis Number	KMHDG41C6EU968354
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Elantra
Model Year	2014
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2021 CRACKED.	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2016 EXPIRED ,CRACKED.	الاطار الخلفي
02 Chassis Condition		الشاسي
02.A Chassis	CHECKED ONLY VISIBLE AREA OK.	الشاسيه
03 Suspension System		ممتص الصدمات
03.A Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
03.B Arms	LOWER ARM BUSHES CRACKED,	ازرع
04 Body		جسم المركبة
04.A Bonnet	REFITTED ,REPAINTED.	غطاء المحرك
04.B Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
04.C Floor	PORTION DENT.	الارضيه
04.D Trunk	REPAIRED ,REPAINTED.	صندوق
04.E Fenders	FRONT BOTH SIDE FENDER REPAIRED ,REPAINTED ,REFITTEED.	مدكار
04.F Other	FRONT BUMPER FRAME ,BULKHEAD REPAIRED.	اخرى
04.G Sign of front accident		وجود مؤشر لحادث في المقدمة

DEFECT	REMARKS	
04.H Bumper	MISALIGN ,PORTION DAMAGE.	دعامية
04.I Paint	BODY PORTION REPAIRED ,PORTION REPAINTED ,DENTS SCRATCHES ,PORTION FADED ,PORTION RUSTY	الصبغ
04.J Sign of back accident		وجود مؤشر لحادث في الخلف
05 Interior Condition		الحالة الداخلية
05.A Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
05.B AC Condition	NOT CHECKED .	المكيف
05.C Odometer reading	NOT CHECKED .	قراءة عداد المسافات
06 Engine Condition		المحرك
06.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,,OIL LEAK.	حالة المحرك النظري
07 Lights		الاضاءة
07.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
08 Transmission Condition		الجير
08.A Road Test	NOT CHECKED .	فحص علي الطريق
08.B Visual Gear Box Condition	NOT CHECKED, MINOR OIL LEAK.	حالة الجير النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.