



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Sep 2022, 12:27:34
Transaction Number	13386690 (CC10006)	Queue Number	595870



Chassis Number	1N4AL3A92GC108614
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Altima
Model Year	2016
Color	White
Mileage	217815 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE PORTION REPAIRED ,REPAINTED ,REFITTED.	مدكار
01.B Bonnet	REFITTED PORTION REPAINTED ,REPAINTED.	غطاء المحرك
01.C Doors	FRONT BOTH SIDE PORTION REPAINTED	أبواب
01.D Sign of front accident		وجود مؤشر لحادث في المقدمة
01.E Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT CROSS MEMBER REPAIRED.	اخرى
01.F Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.G Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY.	صدأ
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03 Exhaust System		نظام العادم
03.A Other	EXHAUST MODIFIED	اخرى
04 Seats Condition		المقاعد

DEFECT	REMARKS	
04.A Seat Condition	SEATS HAVE EXTRA COVER,LEFT SIDE COVER LOOSE.	حالة المقاعد
05 Interior Condition		الحالة الداخليه
05.A AC Condition	OK & AC CONDENSOR DENT	المكيف
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07 Steering Condition		المقود
07.A Axle	BOOT CUT & LEAK	اكسلات
07.B Steering Boot	BOOT CUT	ربلة المقود
08 Suspension System		ممتص الصدمات
08.A Ball Joint	WORN OUT	مفصل كروي
08.B Other	STABILIZER LINK BOOT WORN OUT	اخرى
09 Transmission Condition		الجير
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Visual Gear Box Condition	OK	حالة الجير النظرى
10 Engine Condition		المحرك
10.A Visual Engine Condition	OIL SUMP DENT	حالة المحرك النظرى
11 Brake Condition		الفرامل
11.A Hand Brake	PEDAL BUSH MISSING.	فرامل اليد
12 Chassis Condition		الشاسي
12.A Chassis	FRONT LEFT SIDE CHASSIS OUTER SKIRT REPAIRED.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	1N4AL3A92GC108614
Vehicle Make :	NISSAN
Vehicle Model :	ALTIMA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	217820 Kms.
Origin : United States	Model Year : 2016
Gear Type : Automatic	Engine Size : 3500 CC
Engine No : qr25061158u	Horse 177
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 1850 Kgs.	Empty 1450 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17722847
Inspection Date :	27-09-2022
Certificate Print Date :	27-09-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	7 min 28 sec
Appointment Ref Number :	--
Start Time : 10:34	End Time : 10:42
Lane : 03	Token No. : 123
Attempt : 2	Prints No : 1

Carbon footprint



Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)

24202 KM	2491 L	8296 AED	6.0 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	2500	

Inspection Remarks: body minor scratch & dent front left side fender frame & bulkhead repaired

Payment Details

Inspection Performed by 6831	Payment Method Cash	Transaction Number 17722847	Service Fees AED 70 Collected on 27/09/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

