



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|---------------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 19863904 | Plate Category | : PRIVATE |
| Transaction Date | : 30 MAY 2020 13:27:23 | Plate Number | : 11299 EA |
| Queue Number | : 180529 | Import Doc. Ref. | : |
| Chassis Number | : WWAB13C1BE711299 | Manufacturer/Model | : VOLKSWAGEN/PASSAT |
| Engine Number | : | Model Year | : 2011 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : BROWN |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|--|--------|---------------------------|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Passed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| VISUAL TEST: | | |
| 04 Tires Rims | | الاطارات والعجلات |
| 04.01 - Front Left And Right Hands Tires | | الاطارات الامامية |
| 04.07 - Rims | | الرنجات |
| 05 Body | | الهيكل |
| 05.02 - Paint | | الصبغ |
| 05.05 - Bumpers | | الدعامية |
| 05.09 - Front And Rear Windshields | | الزجاج الامامي والخلفي |
| 06 General Items | | الاشياء العامة |
| 06.14 - Transmission Condition | | حالة ناقل الحركة |
| 06.16 - Engine Condition, Smoke | | حالة المحرك - الدخان |
| 07 Remarks | | ملاحظات |
| 07.04 - Others | | ملاحظات اخرى |
| 09 Auction | | الفحص الكامل |
| 09.02 - Need Wheel Alignment | | بحاجة الى ميزانية العجلات |
| 09.06 - Chassis Ok | OK | الشاصي جيد |
| 09.16 - Sign Of Side Accident | | أثر حادث في جوانب المركبة |
| 09.25 - Body Repainted | | أثر صبغ في المركبة |
| The Test Certificate Shows the test Result at the time of inspection only. | | |