



### Test Certificate

Site Number	: 756-TASJEEL SHARJAH	Plate Code	:
Transaction Number	: 18563567	Plate Category	:
Transaction Date	: 19 NOV 2019 10:14:46	Plate Number	:
Queue Number	: 119233	Import Doc. Ref.	: 504522 DXB
Chassis Number	: JTMHU09LJ7B504522	Manufacturer/Model	: TOYOTA/LAND CRUISER
Engine Number	:	Model Year	: 2007
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION	Mileage	: 262570

Statement of Vehicle Condition

Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفرامل
13.04 - Brake Test	Passed		فحص الفرامل
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
17 Shock Absorbers Test			فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed		فحص مخمد الصدمات
VISUAL TEST:			
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		ALL TYRES WORN OUT WEAK 2015/2017.	الاطارات الامامية
05 Body			الهيكل
05.01 - Rusty		CHASSIS FRAME RUSTY.	الصدأ
05.03 - Doors		FRONT LHS DOOR POWER WINDOW SWITCHES NOT WORKING.	الابواب
05.04 - Fenders		FRONT FENDER FRAMES,BULK HEAD REPAIRED.	المدكار
05.06 - Roof		SUN ROOF NOT WORKING.	السقف
06 General Items			الاشياء العامة
06.10 - Mirrors Side View		B/S NOT WORKING.	المرآيا الجانبية
06.12 - Seats Condition And Seats Fixing		DRIVER SEAT NOT ADJUSTING.	المقاعد وحالتها وتثبيتها
06.16 - Engine Condition, Smoke		WHITE SMOKE.	حالة المحرك - الدخان
09 Auction			الفحص الكامل
09.06 - Chassis Ok	OK		الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK		فحص حالة الماكينة والجبر
09.14 - Sign Of Front Accident			أثر حادث في مقدمة المركبة
09.17 - Defect In 4wd Gear	NOT WORKING.		عطل في الدفع الرباعي
09.25 - Body Repainted		BODY ALL PORTION REPAINTED EXCEPT ROOF,TAIL DOOR.	أثر صيغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط