CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941976
Transaction Date	04 Nov 2026, 14:24:37
Site Name	840 - Emirates Auctions
Transaction Number	99388019 (CC10009) (CC10011)



Vehicle Details

Chassis Number	WAUACCFL3E*******
Specification	GCC Specification
Make	Audi
Model	A4
Model Year	2014
Color	Unknown
Mileage	265687 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE,REAR LEFT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY MUDDY PORTION DENT	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.H Trunk	REAR SWITCH NOT WORKING,PORTION REPAIRED REPAINTED	صندوق
01.I Vehicle Color	BLACK	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	SHAKING OIL LEAK OPEN REFITTED SHAKING OVERHEAT WATER OIL MIXED, FLOWING FROM COOLANT TANK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION WORN OUT,REAR SEATS LOOSE CHILD LOCK DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK REFITTED GETTING JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Steering Condition		المقود
07.A Steering Oil	OIL LEAK	زيت المقود
07.B Steering Boot	BOOT CUT	ربلة المقود
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)/ CENTER CONSOLE BOX COVER DAMAGED,CUP HOLDER PANEL WORN OUT & REAR CONSOLE BOX BACK PANEL PORTION DAMAGED	اخري
08.B AC Condition	NO COOLING	المكيف
08.C Roof Light	NOT WORKING	أنارة السقف
08.D Dash Board	PORTION MINOR WORN OUT	لوحة القياده
08.E Roof Ceiling	REPLACED PORTION LOOSE	بطانه السقف
08.F Sun Visor	BOTH SIDE MIRROR CASE PORTION CRACK	حاجب الشمس
08.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.I Gear Shifting Lever	KNOB WORN OUT,DUST COVER PORTION CRACKED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae