



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **29 Dec 2021, 18:00:20**
 Transaction Number **19374436 (CC10006)** Queue Number **312309**



Chassis Number **1GKFK33J39J120297**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **GMC**
 Model **Yukon**
 Model Year **2009**
 Color **Red**
 Mileage **85923 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE PORTION REPAINTED & REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,DENT,SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS GETTING RUSTY	صدأ
02 Interior Condition		الحالة الداخليه
02.A Mirror	BOTH SIDE FOLDING NOT WORKING & LEFT SIDE MIRROR LOOSE	المرابا
02.B Dash Board	DASHBOARD PORTION CRACKED	لوحة القيادة
02.C AC Condition	OK	المكيف
03 Lights		الاضاءة
03.A Tail Light	REAR RIGHT SIDE COVER CRACKED	الانارة
03.B Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
03.C Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
04 Seats Condition		المقاعد
04.A Seat Belt	OK	حزام الأمان

DEFECT	REMARKS	
04.B Seat Condition	OK	حالة المقاعد
05 Wipers and Arms		المساحات
05.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Gear Box	OK	الجير
07 Battery Condition		حالة البطارية
07.A Battery Condition	OK	حالة البطارية
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2018/2019 WORN OUT	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2017 CRACKED	الاطار الخلفي
08.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
09 Steering Condition		المقود
09.A Steering Boot	BOOT LEAK	ريلة المقود
09.B Axel	BOOT CUT & LEAKING	اكسلات
09.C Tie Rod End	BUSHES CUT	مؤخرة الرودادات
09.D Other	STABILIZER CUT	اخرى
10 Engine Condition		المحرك
10.A Engine Condition	SIGN OF LEAK	حالة المحرك
11 Chassis Condition		الشاسي
11.A Chassis	CHASSIS FRAME COMPLETELY RUST PROOFED & RUSTY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.