CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945062
Transaction Date	09 Nov 2026, 13:03:27
Site Name	840 - Emirates Auctions
Transaction Number	33649625 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JTGSX22P75*******
Specification	GCC Specification
Make	Toyota
Model	Hiace
Model Year	2005
Color	White
Mileage	374521 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY., RUSTY HOLE	الارضية
01.D Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.E Pillars	DOOR PILLAR ROCKER PANEL REPAIRED	القوائم
01.F Fuel Tank	DAMAGED.	خزان الوقود
01.G Sign of front accident	FRONT BUMPER FRAME , FIREWALL COWL PANEL ,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS UPPORT SKIRT REPAIRED DENT GETTING RUSTY.	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT.	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL LEAK , ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED. .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025 CRACKED.	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Leaf Spring	BUSHES CUT .	
08.C Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK ,HARD STEERING.	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
10.B AC Condition	NOT COOLING.	المكيف
10.C Dash Board	GLOVE BOX DAMAGED	لوحة القياده
10.D Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر

wecare@carscheck.ae