



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 May 2023, 16:28:23
Transaction Number	87485601 (CC10006)	Queue Number	716312



Chassis Number	MROCX8CD2J0693520
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Hilux
Model Year	2018
Color	White
Mileage	497663 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	LOW COOLING,	المكيف
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OIL WET	حالة الجير النظري
02.C Gear Box Mount	BUSH CRACKED	كرسي الجير
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2021,	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي
04 Engine Condition		المحرك
04.A Visual Engine Condition	OK	حالة المحرك النظري
05 Body		جسم المركبة
05.A Floor	REAR CARRIOR BOX PORTION REPAIRED, REPAINTED	الارضية

DEFECT	REMARKS	
05.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED ,PORTION RUSTY	الصبغ
05.C Doors	REAR BOTH SIDE REPAINTED PORTION REPAIRED	أبواب
05.D Bumper	MISALIGN	دعامية
06 Chassis Condition		الشاسيه
06.A Chassis	OK	الشاسيه
07 Suspension System		ممتص الصدمات
07.A Ball Joint	BOOT CUT	مفصل كروي
07.B Arms	LOWER ARM BUSHES CRACKED	ازرع
08 Lights		الاضاءة
08.A Tail Light	LEFT SIDE CRACKED	الانارة
09 Seats Condition		المقاعد
09.A Seat Condition	PORTION DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.