

Queue Number 2890760

Transaction Date 20 Oct 2026, 14:30:08

Site Name
840 - Emirates AuctionsTransaction Number
69239613 (CC10009) (CC10012)

Vehicle Details

Chassis Number	2C3CDXBG6M*****
Specification	Imported
Make	Dodge
Model	Charger
Model Year	2021
Color	White
Mileage	121793 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE , REAR BOTH SIDE REPAINTED PORTION REPAIRED , FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES & PORTION STICKER	الصبغ
01.C Doors	FRONT RIGHT SIDE , REAR BOTH SIDE REPAINTED PORTION REPAIRED , RIGHT SIDE BOTH REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION DENT RIGHT SIDE PORTION RUNNING BOARD REPAIRED	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	SING REFITTED	غطاء المحرك
01.H Pillars	RIGHT SIDE PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	MISALIGN	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED PORTION DENT	الشاسية
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OILWET PARTS REFITTED GETTING RUSTY, MINOR SHAKING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	PARTS GETTING RUSTY, MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	RIGHT SIDE MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Interior Condition		الحالة الداخلية
07.A Other	INTERIOR PARTS RUSTY , (INTERIOR REFITTED)	اخرى
07.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING	المرايا
07.C AC Condition	OK	المكيف
07.D Roof Ceiling	PORTION LOOSE , MINOR CUT	بطانة السقف
07.E Air Bag	REFITTED	وسائد هوائية
07.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae