



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 13 Jan 2022, 18:07:46 |
| Transaction Number | 44562258 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | 1FTEX1E6XAFD67605 |
| Engine Number | |
| Vehicle Class | Heavy |
| Manufacturer | Ford |
| Model | F 150 RAPTOR |
| Model Year | 2010 |
| Color | Black |
| Mileage | 132224 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|-----------------------------|--|----------------------|
| 01 Body | | جسم المركبة |
| 01.A Fenders | REAR CARRIER BOX REPAINTED,PORTION REPAIRED&FRONT FENDER FIBER PAINT CANNOT CHECK & FRONT BOTH SIDE REFITTED | مدكار |
| 01.B Bonnet | FIBER PAINT CANNOT CHECK,REFITTED | غطاء المحرك |
| 01.C Doors | REPAINTED | أبواب |
| 01.D Trunk | PORTION REPAIRED,REPAINTED | صندوق |
| 01.E Paint | BODY PORTION REPAINTED,PORTION REPAIRED, MINOR DENT,SCRATCHES | الصبغ |
| 01.F Roof | REPAINTED | السقف |
| 02 Battery Condition | | حالة البطارية |
| 02.A Battery bracket | BATTERY BRACKET MISSING | حامل البطارية |
| 02.B Battery Condition | OK | حالة البطارية |
| 03 Lights | | الاضاءة |
| 03.A Head Light | ALL LIGHT WORKING | الاضاءة الرئيسية |
| 03.B Warning Light | WARNING LIGHT ON IN DISPLAY | ضوء تحذير |
| 04 Chassis Condition | | النشاصي |

| DEFECT | REMARKS | |
|---|--|----------------------------|
| 04.A Chassis | RIGHT SIDE MIDDLE INNER CHASSIS MINOR DENT | الشاسيه |
| 05 Transmission Condition | | |
| 05.A Gear Box | REFITTED,SIGN OF MINOR OIL LEAK | الجير |
| 05.B Road Test | NOT CHECK | فحص علي الطريق |
| 06 Exhaust System | | |
| 06.A Modification | MODIFIED&TAIL PIPE MISSING | تعديلات |
| 07 Interior Condition | | |
| 07.A Steering Wheel and control buttons | WORN OUT & HORN NOT WORKING | عجلة القيادة وازرار التحكم |
| 07.B AC Condition | OK | المكيف |
| 07.C Mirror | LEFT SIDE ADJUSTMENT NOT WORKING & VIEW MIRROR LOOSE | المرايا |
| 08 Tires and Rims Condition | | |
| 08.A Front Tyre | BOTH SIDE 2014 & EXPAIRED, CRACKED | الاطار الامامي |
| 08.B Rear Tyre | BOTH SIDE 2014 & EXPAIRED, CRACKED | الاطار الخلفي |
| 08.C Rims Condition | RIMS HAVE MINOR SCRATCHES | حالة الجنوط |
| 09 Suspension System | | |
| 09.A Arms | FRONT LOWER ARM BUSHED CRACKED | ازرع |
| 10 Engine Condition | | |
| 10.A Engine Condition | REFITTED | حالة المحرك |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Possession Certificate : 65507048

Chassis No : 1FTEX1E6XAFD67605

Vehicle Make : FORD

Vehicle Model : F-150

Vehicle Class : Light Vehicle

Body Type : PICK-UP

Fuel : Benzene

Color : Black

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 132225 Kms.

Origin : United States Model Year : 2010

Gear Type : Automatic Engine Size : 6800 CC

Engine No : AFD67605 Horse Power : 411

Axles No : 2 Cylinders : 8

No Of Doors : 4 No Of Seats : 5

G. V. W. : 3000 Kgs. Empty Weight : 1600 Kgs.

Certificate Number : 5-TAS-2022-15909299

Inspection Date : 17-01-2022

Certificate Print Date : 17-01-2022

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Al Aweer

Total Time Taken :
14 min 17 sec

Appointment Ref Number : --

Start Time : 10:10

End Time : 10:24

Lane : 01

Token No. : 120

Attempt : 1

Prints No : 1

Parameter Readings

Service brake imbalance on
front axle
4 %

Service brake imbalance on
rear axle
7 %

Parking brake imbalance
between LHS and RHS
1 %

Vehicle on Petrol CO
Reading
0 %

Vehicle on Petrol HC
Reading
0 PPM VOL

Inspection Findings

Defects

Tire

Issue

Date of manufactured tampered or
expired

Severity

Major

CHANGE ALL 4 TIRE 2014.

Discrepancies

Engine Size Discrepancy in Engine Size

Old Value

6800

New Value

6200

Verified

Inspection Remarks: UNDER BODY MINOR RUSTY.

Payment Details

Inspection Performed by
37084

Payment Method
Cash

Transaction Number
15909299

Service Fees
AED 170 Collected on 17/01/2022

Parking Slot No
--

Service Name
Registration Test

Attempt
1

Received by
Hussain Basha Akeel

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

