

Queue Number

2771678

Transaction Date

18 Sep 2026, 15:13:32

Site Name

840 - Emirates Auctions

Transaction Number

13209015 (CC10006) (CC10006)



Vehicle Details

Chassis Number

WP1ZZZ92ZD*****

Specification

GCC Specification

Make

Porsche

Model

Cayenne

Model Year

2013

Color

Black

Mileage

188257 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

FRONT BOTH SIDE REPAINTED, PORTION REPAIRED,REFITTED

مدكار

01.B Paint

BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES PORTION GETTING FADED RUSTY

الصبغ

01.C Doors

RUBBERS SENSOR MISSING,

أبواب

01.D Rusty

UNDER BODY PARTS, SUSPENTION GETTING RUSTY

صدأ

01.E Floor

UNDER BODY FULLY COVERD, MUDDY

الارضية

01.F Bonnet

REFITTED, REPAINTED, REPAIRED, SHOCK NOT WORKING

غطاء المحرك

01.G Other

FRONT BUMPER FRAME , BULKHEAD ,RADIATOR SUPPORT ASSMPLY REFITTED

اخرى

01.H Trunk

AUTO NOT WORKING

صندوق

01.I Sign of front accident

وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis

CHASSIS COVERED MUDDY OILY PORTION , RIGHT SIDE END OPEN DETACHED, GETTING RUSTY

الشاسيه

02.B Other

FOR FULL INSPECTION NEED TO REMOVE UNDER ALL COVER ,STEAM WASH FOR RECHECK

اخرى

03 Engine Condition

المحرك

03.A Mount

BUSHES CRACKED

كرسي

03.B Smoke

WHITE

دخان

03.C Engine Visual Condition

SHAKING, ABNORMAL NOISY,,REFITTED,OIL LEAK,PARTS RUSTY

الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	JERKING, ,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
05.B Gear Box Mount	BUSH CRACKED	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023/2024 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك و طنايبير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CUT	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Steering Box	LEAK	جهاز المقود
10.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
10.C Axle	BOOT CUT	اكسلات
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
11.B Mirror	LEFT SIDE GETTING FADED	المرايا
11.C AC Condition	OK, GRAIL PORTION DAMAGED	المكيف
11.D Power Window Switch And Glass	CHROM MISSING, QUATER GLASS RUBBER DAMAGED, REAR CURTAIN PORTION DAMAGED	مفتاح النافذه و الزجاج
11.E Dash Board	SIGN OF MULTED, LEATHER WORN OUT	لوحة القيادة
11.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae