

Queue Number

2830552

Transaction Date

03 Oct 2026, 13:01:06

Site Name

840 - Emirates Auctions

Transaction Number

82557145 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JTGHN9CP3P*****
Specification	GCC Specification
Make	Toyota
Model	Hiace
Model Year	2023
Color	White
Mileage	162882 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE QUARTER PANEL REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED, MINOR DENTS SCRATCHES ON BODY .	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	FLOOR, RIGHT SIDE RUNNING BOARD PORTION DENT . MUDDY.	الارضية
01.E Bumper	MISALIGNED, MINOR SCRATCHES /. FRONT LOWER GRILL MISSING.	دعامية
01.F Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION MUDDY PORTION COVERD, VISIBLE AREA OK.	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK GET SHAKING. PARTS GETTING RUSTY.	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DIRTY PORTION LOOSE.	حالة المقاعد
---------------------	----------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	OIL WET , PARTS MINOR RUSTY.	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 RIGHT SIDE DAMAGED ,WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023/2024 WORN OUT .	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED.	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE DAMAGED.	الضوء الخلفي
07.C Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER.	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY.	دواسة الفرامل
08.B Disc&Drum	PARTS GETTING RUSTY.	دسك وطناير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	MINOR LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR CONDITION RUSTY ,DIRTY .	اخرى
10.B AC Condition	NORMAL COOLING.	المكيف
10.C Roof Ceiling	PORTION DIRTY	بطانة السقف
10.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوى والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae