

Queue Number

2837711

Transaction Date

06 Oct 2026, 15:01:05

Site Name

840 - Emirates Auctions

Transaction Number

78295147 (CC10013) (CC10011)



Vehicle Details

Chassis Number

WBSKW8102H*****

Specification

GCC Specification

Make

BMW

Model

X6

Model Year

2017

Color

Unknown

Mileage

N/A NA

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY TOTALLY PROTECTION STICKER PAINT NOT CHECK,STICKER PORTION DAMAGED FADED(BODY KIT MODIFIED)	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COMPLETELY COVERED MUDDY DIRTY MINOR DENT	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Other	BODY LEVEL LOW	اخرى
01.F Trunk	NOT OPEN	صندوق
01.G Vehicle Color	BLUE	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FULLY COVERED MUDDY DIRTY FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER ENGINE COVER FOR RECHECK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	NOT START ALL SYSTEM NOT CHECK , REFITTED , PARTS GETTING RUSTY , MUDDY , DIRTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECK , RFEITTED , PARTS GETTING RUSTY , MUDDY , DIRTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT 2022 DRY CRACK RIGHT 2024 CRACK	الاطار الامامي
06.B Rear Tyre	LEFT 2024 RIGHT 2022 DRY CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES / EXTRA SPACER	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
08.C Other	SUSPENSION PARTS REFITTED	اخرى
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS DIRTY GETTING RUSTY	اخرى
09.B AC Condition	NOT CHECKED	المكيف
09.C Odometer reading	NOT CHECKED	قراءة عداد المسافات
09.D Door Panel	GETTING WORN OUT	لوحة بطانة الباب
09.E Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	WATER EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae