



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>01 Aug 2022, 18:18:13</b>
Transaction Number	<b>85804751 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WDB2304751F115495</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>S 500</b>
Model Year	<b>2006</b>
Color	<b>Black</b>
Mileage	<b>90455 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>Japan Imported</b>

DEFECT	REMARKS	
<b>01 Steering Condition</b>		<b>المقود</b>
01.A Steering Oil	POWER STEERING MAJOR OIL LEAK, STREERING HARD	زيت المقود
01.B Tie Rod End	BOOT CUT	مؤخرة الروداد
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظري
02.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A Dash Board	WORN OUT . PORTION LOOSE	لوحة القيادة
03.B AC Condition	OK	المكيف
<b>04 Chassis Condition</b>		<b>الشاصي</b>
04.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>05 Body</b>		<b>جسم المركبة</b>
05.A Paint	BODY PORTION REPAINTED MINOR DENT,SCRATCHES	الصبغ
05.B Floor	UNDER BODY FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضيه
05.C Bonnet	PORTION REPAINTED	غطاء المحرك

DEFECT	REMARKS	
<b>06 Tires and Rims Condition</b>		الاطارات
06.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>07 Battery Condition</b>		حالة البطارية
07.A Battery bracket	MISSING	حامل البطارية
<b>08 Transmission Condition</b>		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
08.C Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
<b>09 Suspension System</b>		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CRACKED	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
<b>10 Lights</b>		الاضاءة
10.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.