CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2919583
Transaction Date	29 Oct 2026, 13:23:40
Site Name	840 - Emirates Auctions
Transaction Number	72903177 (CC10013) (CC10019)



Vehicle Details

Chassis Number	WP0ZZZ97ZD*******
Specification	GCC Specification
Make	Porsche
Model	Panamera GTS
Model Year	2013
Color	Red
Mileage	95360 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT RIGHT SIDE PORTION REPAINTED & REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED / COVER PORTION DAMAGED	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.H Door Handle &Lock	FRONT RIGHT SIDE OUTER HANDLE COVER PORTION DAMAGED	مقابض الأبواب والأقفال
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY , OIL PAN REPAIRED	الحالة النظريه للمحرك
04 Exhaust System		**نظام العادم**
04.A Modification	EXHAUST SYSTEM MODIFIED NOISY	تعديلات
04.B Catalytic Converter	MISSING	دبة البيئة
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	BOTH SIDE CRACKED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	REFITTED	
08.B Arms	ARM BUSHES MINOR DRY CRACK	ازرع
08.C Ball Joint	BOOT DRY CRACK	مفصل كروي
08.D Hydraulic System	NOT WORKING	النظام الهيدروليكي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A AC Condition	OK	المكيف
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	WATER EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae