CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3012778
Transaction Date	20 Nov 2026, 13:19:20
Site Name	840 - Emirates Auctions
Transaction Number	98150768 (CC10009) (CC10019)



Vehicle Details

Chassis Number	2G1F91E37F*******
Specification	GCC Specification
Make	Chevrolet
Model	Camaro
Model Year	2015
Color	Black
Mileage	89563 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	BOTH SIDE REPAINTED,	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION DENT	الارضية
01.F Trunk	SHOCK NOT WORKING	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	REFITTED GETTINGRUSTY,JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	LEFT SIDE 2023 CRACKED & RIGHT SIDE 2025	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Tail Light	LEFT SIDE PORTION DAMAGED	الضوء الخلفي
06.B Fog light	RIGHT SIDE MISSING	كشاف الضباب
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CUT	ازرع
08 Steering Condition		المقود
08.A Other	STEERING GETTING HARD HAVE PLY	اخري
09 Interior Condition		الحاله الداخليه
09.A Other	INETRIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
09.B AC Condition	OK	المكيف
09.C Dash Board	LEATHER MINOR WORN OUT PORTION LOOSE	لوحة القياده
09.D Door Panel	PORTION LOOSE	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae