



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 May 2023, 17:01:49
Transaction Number	39661797 (CC10013)	Queue Number	724346



Chassis Number	KM8SB12B93U536882
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Santa Fe
Model Year	2003
Color	Black
Mileage	179790 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Power Window Switch	FRONT BOTH SIDE NOT WORKING	مفتاح النافذه
01.B Odometer reading	SCREEN FADED	قراءة عداد المسافات
01.C Roof Light	REAR DAMAGED	أنارة السقف
01.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.E AC Condition	NOT WORKING GRILL DAMAGED	المكيف
01.F Roof Ceiling	LOOSE	بطانه السقف
02 Engine Condition		المحرك
02.A Smoke	WHITE	دخان
02.B Visual Engine Condition	OIL LEAK ABNORMAL NOISY	حالة المحرك النظري
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	NOT CHECK	حالة الجير النظري
04 Lights		الاضاءة
04.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية

DEFECT	REMARKS	
04.B Fog light	FADED	كشاف الضباب
04.C Tail Light	RIGHT SIDE DAMAGED	الانارة
05 Battery Condition		حالة البطارية
05.A Battery bracket	MISSING	حامل البطارية
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	CRACKED DAMAGED	الاطار الامامي
06.B Rear Tyre	CRACKED DAMAGED	الاطار الخلفي
07 Body		جسم المركبة
07.A Paint	BODY PORTION REPAINTED PORTION REPAIRED PORTION RUSTY & FADED MINOR DENT SCRATCHES	الصبغ
07.B Other	VISUAL TEST ONLY	اخرى
07.C Floor	UNDER FLOOR CHASSIS SUSPENSION PARTS NOT CHECK	الارضية
08 Chassis Condition		الشاسي
08.A Chassis	NOT CHECK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.