

Queue Number 2569748

Transaction Date 24 Jul 2026, 12:23:35

Site Name
840 - Emirates AuctionsTransaction Number
80355507 (CC10006) (CC10019)

Vehicle Details

Chassis Number	1G1FB1RS3L*****
Specification	Imported
Make	Chevrolet
Model	Camaro
Model Year	2020
Color	Blue
Mileage	84832 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES, PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT, PORTION RUSTY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Windshield	FRONT CRACKED	زجاج
01.F Pillars	BOTH SIDE DOOR PILLARS, ROCKER PANEL, WHEEL ARCH REPAIRED	القوائم

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS LOWER EDGE DENT, GETTING RUSTY	الشاسيه
02.B Other	FOR FULL INSPECTION NEED TO REMOVE FRONT LEFT SIDE FENDER COVER	اخرى

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED	كرسي
03.B Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED, REFITTED, OIL WET, PARTS RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد
---------------------	-----------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL WET,PARTS RUSTY	الحالة النظرية للجير
05.B Gear Box Mount	BUSH CRACKED	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CUT	ازرع
08.B Ball Joint	BOOT CRACKED	مفصل كروي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الروداد
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخرى
10.B Mirror	CENTER MIRROR PORTION DAMAGED	المرآيا
10.C AC Condition	NOT CHECKED	المكيف
10.D Dash Board	PORTION WORN OUT	لوحة القيادة
10.E Door Panel	PORTION CRACKED	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

