



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **22 Jan 2023, 13:54:39**
 Transaction Number **96202854 (CC10006)** Queue Number **657771**



Chassis Number **JT6HF10U6Y0101203**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Lexus**
 Model **RX 300**
 Model Year **2000**
 Color **--**
 Mileage **001 Miles**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **Imported**

DEFECT	REMARKS	
01 Suspension System		ممتص الصدمات
01.A Shock Absorber	WEAK & LEAK .	ممتص الصدمات
01.B Arms	LOWER ARM BUSHES CRACKED .	ازرع
02 Interior Condition		الحالة الداخلية
02.A Dash Board	PORTION DAMAGED .	لوحة القيادة
02.B Sun Visor	LOOSE .	حاجب الشمس
02.C AC Condition	NOT CHECKED ,GRILL PORTION DAMAGED .	المكيف
02.D Odometer reading	NOT CHECKED .	قراءة عداد المسافات
02.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
02.F Door Panel	PORTION LOOSE .	لوحة بطانة الباب
02.G Mirror	LEFT SIDE FADED.	المرآيا
03 Tires and Rims Condition		الاطارات
03.A Rear Tyre	BOTH SIDE 2021/2017 EXPIRED ,CRACKED .	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2020/2017 EXPIRED,CRACKED .	الاطار الامامي
04 Body		جسم المركبة
04.A Paint	BODY PORTION REPAIRED ,REPAINTED ,MINOR	الصبغ

DEFECT	REMARKS	
	DENTSSCRATCHES ,PORTION RUSTY , PORTION FADED .	
04.B Floor	PORITON DENT . BACK PANEL ,QUARTER PANEL ,COMPARTMENT FLOOR ,QUARTER PANEL ,WHEEL ARCH REPAIRED ,KINK , GETTING RUSTY .	الارضية
04.C Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .	صدأ
04.D Bonnet	GRILL DAMAGED,SHOCK WEAK .	غطاء المحرك
04.E Sign of front accident		وجود مؤشر لحادث في المقدمة
04.F Sign of back accident		وجود مؤشر لحادث في الخلف
04.G Vehicle Color	GRAY.	لون المركبة
04.H Bumper	MISALIGN PORITON DAMAGE.	دعامية
04.I Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	اخرى
05 Lights		الاضاءة
05.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
06 Engine Condition		المحرك
06.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED,KEY MISSING . REFITTED OILLEAK .	حالة المحرك النظري
06.B Mount	CRACKED .	كرسي
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	NOT CHECKED & REFITTED OIL LEAK .	حالة الجير النظري
07.B Road Test	NOT CHECKED .	فحص علي الطريق
08 Steering Condition		المقود
08.A Steering Boot	BOOT CUT.	ربلة المقود
08.B Steering Box	OIL LEAK.	جهاز المقود
09 Chassis Condition		الشاسي
09.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
10 Seats Condition		المقاعد
10.A Seat Condition	DAMAGE .	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.