



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	07 Jan 2022, 12:03:58
Transaction Number	66080240 (CC10006)	Queue Number	312309



Chassis Number	SCBCE63W86C039074
Engine Number	
Vehicle Class	Car
Manufacturer	Bentley
Model	Continental
Model Year	2006
Color	Red
Mileage	107245 Km
Fuel Type	Petrol
No. Of Cylinders	12
Specification	GCC Specification

DEFECT	REMARKS	
01 Wipers and Arms		المساحات
01.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
02 Interior Condition		الحالة الداخليه
02.A AC Condition	OK	المكيف
02.B Mirror	FOLDING NOT WORKING	المرايا
02.C Other	CENTER CONSOLE BOX COVER DAMAGED LOOSE& REAR CONSOLE BOX DAMAGED,MISSING & GEAR SHIFTING LEVER DUST COVER MISSING	اخرى
02.D Steering Wheel and control buttons	MINOR WORN OUT	عجلة القيادة وازرار التحكم
02.E Sun Visor	LEFT SIDE BRACKET COVER LOOSE	حاجب الشمس
03 Lights		الاضاءة
03.A Head Light	OK	الاضاءة الرئيسية
03.B Indicator & Hazard light	HAZARD LIGHT NOT WORKING	الاشارات
04 Seats Condition		المقاعد
04.A Seat Belt	OK	حزام الأمان
04.B Seat Condition	OK	حالة المقاعد

DEFECT	REMARKS	
05 Body		جسم المركبة
05.A Bonnet	REFITTED	غطاء المحرك
05.B Trunk	REFITTED,MISALIGN,NOT WORKING PROPERLY	صندوق
05.C Bumper	REPAINTED	دعامية
05.D Fenders	REAR BOTH SIDE PORTION REPAINTED&FRONT FENDER FIBER PAINT CANNOT CHECK	مدكار
05.E Paint	BODY PORTION REPAINTED	الصبغ
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2019 BADLY WORN OUT & RIGHT SIDE CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2019 MINOR CRACKED	الاطار الخلفي
06.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
07 Engine Condition		المحرك
07.A Engine Condition	MINOR OIL LEAK	حالة المحرك
08 Chassis Condition		الشاسي
08.A Chassis	VISIBLE AREA OK	الشاسيه
09 Transmission Condition		الجير
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Gear Box	OK	الجير
10 Battery Condition		حالة البطارية
10.A Battery Condition	OK	حالة البطارية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.