

Queue Number

2869171

Transaction Date

15 Oct 2026, 12:31:30

Site Name

840 - Emirates Auctions

Transaction Number

74650602 (CC10009) (CC10012)



Vehicle Details

Chassis Number	WAUAFCF1E*****
Specification	GCC Specification
Make	Audi
Model	A6
Model Year	2014
Color	Black
Mileage	239717 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE , REAR LEFT REPAINTED PORTION REPAIRED , REAR RIGHT SIDE PORTION DENT , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Doors	FRONT RIGHT SIDE , REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS FULLY MUDDY DIRTY, COVERED & OILY NOT VISIBLE	الارضية
01.F Bumper	MISALIGN , PORTION CRACK	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , SHOCK WEAK NOT WORK	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY MUDDY DIRTY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH PROPERLY, & REMOVE UNDER FLOOR CHASSIS FENDERS COVERS FOR RECHECK PROPERLY	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED SHAKING , FULLY MUDDY DIRTY GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK , REAR CENTER STAND PORTION DAMAGED	حالة المقاعد
---------------------	---	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL WET REFITTED FULLY MUDDY GETTING RUSTY JERKING, DELAY SHIFTING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES , FRONT BOTH SIDE HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LEFT SIDE PORTION CRACK , RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE CRACK	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.D Fog light	NOT WORKING	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	REAR LEAK	ممتص الصدمات
08.B Other	SUSPENSION GETTING RUSTY	اخرى
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY , INTERIOR REFITTED , CENTER CONSOLE BOX SLIDING COVER STRIP MISSING	اخرى
10.B Mirror	CENTER MIRROR STAND DAMAGED	المرآيا
10.C AC Condition	OK , REAR NOT WORKING	المكيف
10.D Roof Ceiling	PORTION LOOSE	بطانة السقف
10.E Door Panel	WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	WORN OUT , DUST COVER CRACK	ذراع نقل السرعات
10.H Engine Start Button	BUTTON DAMAGED	زر تشغيل المحرك
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	SIGN OF OIL WATER MIXED	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae