



TEST CERTIFICATE

| | | | |
|--------------------|-----------------------|------------------|-----------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 20 Jun 2022, 19:09:14 |
| Transaction Number | 75715744 (CC10006) | Queue Number | 312309 |



| | |
|------------------|-------------------|
| Chassis Number | JTHB21B13K2046894 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Lexus |
| Model | ES 300 |
| Model Year | 2019 |
| Color | Black |
| Mileage | 136746 Km |
| Fuel Type | Hybrid |
| No. Of Cylinders | 4 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|---|--------------------|
| 01 Body | | جسم المركبة |
| 01.A Paint | DENTS, SCRATCHES ON BODY | الصبغ |
| 01.B Floor | UNDER BODY FULLY COVERD & VISABLE AREA ONLY CHECK | الارضية |
| 01.C Bumper | MISALIGN | دعامية |
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Front Tyre | BOTH SIDE 2020/2019 | الاطار الامامي |
| 02.B Rear Tyre | BOTH SIDE 2019 CRACKED, WORN OUT | الاطار الخلفي |
| 03 Chassis Condition | | الشاصي |
| 03.A Chassis | VISABLE AREA OK | الشاسيه |
| 04 Engine Condition | | المحرك |
| 04.A Visual Engine Condition | OK | حالة المحرك النظري |
| 04.B Other | UNDER ENGINE COVER | اخرى |
| 05 Interior Condition | | الحاله الداخليه |
| 05.A AC Condition | OK | المكيف |



- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.