



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 Jan 2022, 17:52:20
Transaction Number	91899272 (CC10006)	Queue Number	312309



Chassis Number	1GCNK9E02CZ331885
Engine Number	
Vehicle Class	Heavy
Manufacturer	Chevrolet
Model	Silverado
Model Year	2012
Color	Black
Mileage	190526 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Doors	BOTH SIDE REPAINTED,PORTION REPAIRED	أبواب
01.C Fuel Tank	SIGN OF FUEL LEAK	خزان الوقود
01.D Bonnet	HAVE STICKER CANOT CHECK PAINT	غطاء المحرك
01.E Floor	REAR CARRIOR BOX REPAINTED,PORTION REPAIRED	الارضية
01.F Roof	HAVE STICKER CANOT CHECK PAINT	السقف
01.G Door Handle &Lock	LEFT SIDE INNER DOOR LOCK HANDLE MISSING	مقابض الأبواب والأقفال
01.H Paint	BODY TOTALY,REPAINTED,EXCEPT ROOF & BONNET & PORTION REPAIRED,MINOR DENTS, SCRATCHES	الصبغ
01.I Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS GETTING MINOR RUSTY	صدأ
01.J Bumper	FRONT LOWER PORTION MODIFIED	دعامية
02 Seats Condition		المقاعد
02.A Other	CONSOLE BOX LOCK DAMAGED	اخرى
02.B Seat Belt	OK	حزام الأمان
02.C Seat Condition	LEFT SIDE SEAT DAMAGED,SIDE ADJUSTMENT LOCK DAMAGED	حالة المقاعد

DEFECT	REMARKS	
03 Lights		الاضاءة
03.A Head Light	LEFT SIDE NOT WORKING	الاضاءة الرئيسية
03.B Tail Light	REAR LEFT SIDE PARK LIGHT NOT WORKING	الانارة
03.C Indicator & Hazard light	FRONT LEFT SIDE INDICATOR NOT WORKING	الاشارات
03.D Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
03.E Fog light	MISSING	كشاف الضباب
04 Chassis Condition		الشاسي
04.A Chassis	OK	الشاسيه
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Interior Condition		الحاله الداخليه
06.A Door Panel	LEFT SIDE DAMAGED & RIGHT SIDE LOOSE	لوحة بطانة الباب
06.B AC Condition	OK	المكيف
06.C Dash Board	DASHBOARD CRACKED	لوحة القيادة
06.D Mirror	LEFT SIDE GLASS CRACKED & CENTER MIRROR LOOSE	المرايا
06.E Steering Wheel and control buttons	WORN OUT & HORN NOT WORKING	عجلة القيادة وازرار التحكم
07 Tires and Rims Condition		الاطارات
07.A Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
07.B Front Tyre	BOTH SIDE 2015/2016 CRACKED & EXPIRED	الاطار الامامي
07.C Rear Tyre	LEFT SIDE 2016 CRACKED,EXPIRED & RIGHT SIDE 2018 MINOR CRACKED	الاطار الخلفي
07.D Rims Condition	RIMS HAVE MINOR SCRATCHES & REAR BOTH SIDE WHEEL HUB COVER MISSING	حالة الجنوط
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	REAR LEFT SIDE SHOCK ABSORBER OIL LEAK	ممتص الصدمات
09 Engine Condition		المحرك
09.A Engine Condition	OK	حالة المحرك
10 Steering Condition		المقود
10.A Steering Oil	OIL LEAK	زيت المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.