



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **08 May 2022, 17:24:05**
 Transaction Number **34043949 (CC10006)** Queue Number **312309**



Chassis Number **WDCYR70F59X179317**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Mercedes**
 Model **G 55**
 Model Year **2009**
 Color **White**
 Mileage **245362 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES & PORTION GETTING RUSTY	الصبغ
01.B Sign of side accident		وجود مؤشر لحادث في الجانب
01.C Other	RIGHT SIDE QATAR PANEL BACK PANEL, WHEEL ARCH REPAIRED	اخرى
01.D Fenders	REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	مدكار
01.E Bonnet	PORTION REPAIRED,REPAINTED	غطاء المحرك
01.F Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
01.G Bumper	BUMPER REPAIRED & LOGO MISSING	دعامية
02 Interior Condition		الحالة الداخليه
02.A AC Condition	NOT WORKING & GRILL DAMAGED	المكيف
02.B Power Window Switch	NOT WORKING	مفتاح النافذه
02.C Sunroof	NOT WORKING	فتحت سقف
02.D Door Panel	LOOSE	لوحة بطانة الباب
02.E Dash Board	DASHBOARD & CONSOLE BOX DAMAGED	لوحة القيادة
02.F Roof Light	CONSOLE BOX DAMAGED	أنارة السقف
02.G Audio	NOT WORKING	صوتيات

DEFECT	REMARKS	
03 Seats Condition		المقاعد
03.A Seat Condition	DRIVER SEAT DAMAGED & FRONT BOTH SIDE SEAT SIDE COVER DAMAGED	حالة المقاعد
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	REFITTED	حالة الجير النظرى
04.C DIFFERENTIAL	REFITTED	الدفرنشل
04.D Gear Box Mount	LOWER GEAR SHIFT LEVER MODIFIED	كرسي الجير
05 Tires and Rims Condition		الاطارات
05.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
05.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
06 Engine Condition		المحرك
06.A Visual Engine Condition	REFITTED	حالة المحرك النظرى
07 Chassis Condition		الشاسي
07.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.