



Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 19023431	Plate Category	: PRIVATE
Transaction Date	: 21 JAN 2020 11:54:12	Plate Number	: 8149 EA
Queue Number	: 137129	Import Doc. Ref.	:
Chassis Number	: KMHJM81D19U928149	Manufacturer/Model	: HYUNDAI/TUCSON
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.13 - Stub Axle Assemblies, Boots		المحور
		FRONT RIGHT AXLE OIL LEAK
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		TIRES 2018
05 Body		الهيكل
05.02 - Paint		الصبغ
		BODY & BUMPER MINOR SCRATCH
06 General Items		الاشياء العامة
06.21 - Battery Condition		حالة البطارية
		BATTERY WEAK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		FRONT DIFFERENTIAL OIL LEAK
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok	OK	الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.25 - Body Repainted		أثر صبغ في المركبة
		BODY PORTIONS REPAINTED
The Test Certificate Shows the test Result at the time of inspection only.		