



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	20 Jan 2023, 11:51:32
Transaction Number	19938191 (CC10010)	Queue Number	657818



Chassis Number	MMBJNKA50DD019477
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	
Model Year	2013
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2019 CRACKED,	الاطار الخلفي
03 Steering Condition		المقود
03.A Steering Oil	OIL LEAK	زيت المقود
03.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
04 Interior Condition		الحاله الداخليه
04.A AC Condition	NOT CHECK	المكيف
04.B Odometer reading	NOT CHECK	قراءة عداد المسافات
04.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
04.D Mirror	LEFT SIDE OUTER COVER DAMAGED	المرايا
05 Body		جسم المركبة
05.A Paint	BODY PORTION REPAINTED,PORION REPAIRED,MINOR DENT,SCRATCHES,PORION RUSTY,PORION FADED	الصبغ

DEFECT	REMARKS	
05.B Pillars	RIGHT SIDE C/PILLAR ROCKER PANEL REPAIRED	القوائم
05.C Rusty	UNDER BODY PARTS SUSPENSION CHASSIS GETTING RUSTY	صدأ
05.D Sign of side accident		وجود مؤشر لحادث في الجانب
05.E Floor	UNDER FLOOR RUST PROOFED & PORTION DENT	الارضية
05.F Vehicle Model	L200	طراز المركبة
05.G Fenders	REFITTED	مدكار
06 Suspension System		ممتص الصدمات
06.A Leaf Spring	LEAF SPRING BUSHES CRACKED,LEAF GETTING RUSTY	
06.B Ball Joint	BOOT CUT	مفصل كروي
06.C Arms	LOWER ARM BUSH CRACKED	ازرع
07 Engine Condition		المحرك
07.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK REFITTED	حالة المحرك النظري
08 Transmission Condition		الجير
08.A Visual Gear Box Condition	NOT CHECK & OIL LEAK REFITTED	حالة الجير النظري
08.B Road Test	NOT CHECK	فحص علي الطريق
09 Chassis Condition		الشاصي
09.A Chassis	OK	الشاسيه
10 Seats Condition		المقاعد
10.A Seat Condition	PORTION DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.