CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877758
Transaction Date	20 Oct 2026, 09:00:31
Site Name	840 - Emirates Auctions
Transaction Number	13703826 (CC10010) (CC10010)



Vehicle Details

Chassis Number	**********
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2009
Color	Silver
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY TOTALLY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END REPAIRED DENT ,REAR BOTH SIDE CHASSIS EXTENSION REPAIRED DENT GETTING RUSTY.	الشاسيه
02.B Chassis Number	VIN CORRECTED,KNMCC42H29P737557	رقم القاعدة
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED.	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED.	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK ,BODY LEVEL HIGH ,	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CRACKED.	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخري
10.B Dash Board	PORTION LOOSE	لوحة القياده
10.C Sun Visor	LOOSE	حاجب الشمس
10.D Odometer reading	NOT CHECKED.	قراءة عداد المسافات
10.E Door Panel	WORN OUT .	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae