CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2922903
Transaction Date	29 Oct 2026, 16:46:52
Site Name	840 - Emirates Auctions
Transaction Number	70925957 (CC10013) (CC10019)



Vehicle Details

Chassis Number	JN8AY2NY6G*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2016
Color	White
Mileage	451002 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY TOTALY,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES,PORTION RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Other	VEHICLE WHILE DRIVE NOISY	اخري
01.G Fuel Tank	LEAK DRIPPING	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME DIRTY GETTING RUSTY PORTION BULGED	الشاسيه
03 Engine Condition		المحرك
03.A Other	UPPER COVER PORTION CRACK	اخري
03.B Engine Visual Condition	REFITTED , PARTS GETTING RUSTY , MUDDY , DIRTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	MINOR DENT	اخري

Condition	Remarks	الحالة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR JERKING ,REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	MINOR LEAK	ممتص الصدمات
09.B Arms	ARM BUSHES DRY CRACK	ازرع
09.C Ball Joint	BOOT CUT	مفصل كروي
09.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودات
10.B Axle	BOOT CUT LEAK	اكسلات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED & CENTER CONSOLE BOX COVER PORTION DAMAGED	اخري
11.B Dash Board	PORTION WORN OUT MELTED,CENTER CONSOLE BOX COVER MISSING	لوحة القياده
11.C Sun Visor	LEFT SIDE MISSING	حاجب الشمس
11.D Door Panel	PORTION DAMAGED,LOOSE	لوحة بطانة الباب
11.E Steering Wheel and control buttons	EXTRA COVER	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	GEAR LOCK COVER MISSING & KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae