CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2905927
Transaction Date	24 Oct 2026, 12:14:04
Site Name	840 - Emirates Auctions
Transaction Number	20508900 (CC10013) (CC10025)



Vehicle Details

Chassis Number	1FTPW12567*******
Specification	Imported
Make	Ford
Model	F 150
Model Year	2007
Color	White
Mileage	61018 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR BOTH SIDE REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.F Bumper	PORTION DENT	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Other	LEFT SIDE FOOT STEP FOLDING NOT WORKING	اخري
01.I Sign of back accident		وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS FRAME DIRTY MUDDY PORTION GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN CHECK DOOR POST STICKER ONLY	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Other	INNER COMPARTMENT ELECTRIC WIRE WORN OUT UNSAFE	اخري
03.B Engine Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Catalytic Converter	CUT REWELDED	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , OIL LEAK , PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LEFT SIDE BRACKET DAMAGED	الاضاءة الرئيسية
08.B Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
09 Suspension System		ممتص الصدمات
09.A Leaf Spring	MISALIGN , BUSHES DRY CRACK	
09.B Arms	ARM BUSHES DRY CRACK	ازرع
09.C Ball Joint	BOOT CUT DRY CRACK	مفصل كروي
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
10.B Mirror	LEFT SIDE GLASS PORTION DAMAGED REPAIRED	المرايا
10.C AC Condition	OK	المكيف
10.D Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
10.E Audio	SCREEN MODIFIED , COVER PANEL LOOSE PART MISSING	صوتيات
10.F Dash Board	PORTION WORN OUT , PART MISSING	لوحة القياده
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Engine Start Button	KEY HOLDER DAMAGED	زر تشغيل المحرك
11 Battery Condition		حالة البطارية
11.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae