

Queue Number

2837276

Transaction Date

12 Oct 2026, 13:41:28

Site Name

840 - Emirates Auctions

Transaction Number

20096751 (CC10010) (CC10010)



Vehicle Details

Chassis Number	MNTBB7A97F*****
Specification	GCC Specification
Make	Nissan
Model	Sentra
Model Year	2015
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED PORTION GETTING RUSTY FADED MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS MUDDY	الارضية
01.D Bumper	MISALIGN ,SCRATCHES, PORTION DAMAGED	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME ,FENDER FRAME , RADIATOR SUPPORT BULK HEAD ,CROSS MEMBER INNER FENDER FRAME REPAIRED .	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL QUARTER PANEL COMPARTMENT AREA REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASIS REPAIRED DENT , REAR BOTH SIDE EXTENSION END REPAIRED DENT KINK.	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CUT .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECK REFITTED OIL LEAK ,PARTS RUSTY .	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK ,PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	EXPIRED CRACKED DAMAGED	الاطار الامامي
05.B Rear Tyre	EXPIRED CEACKED DAMAGED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED.	اخرى
09.B Mirror	CENTER MIRROR LEFT SIDE MIRROR MISSING	المرآيا
09.C AC Condition	NOT CHECKED .	المكيف
09.D Roof Ceiling	PORTION LOOSE.	بطانة السقف
09.E Odometer reading	NOT CHECKED .	قراءة عداد المسافات
09.F Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae