



Test Certificate

| | | | |
|---------------------|--------------------------|--------------------|--------------|
| Site Number | : 840-TASJEEL EM AUCTION | Plate Code | : 0 |
| Transaction Number | : 17921509 | Plate Category | : PRIVATE |
| Transaction Date | : 19 AUG 2019 12:07:46 | Plate Number | : 397321 EA |
| Queue Number | : 93954 | Import Doc. Ref. | : |
| Chassis Number | : 3GTU29EJXFG397321 | Manufacturer/Model | : GMC/SIERRA |
| Engine Number | : | Model Year | : 2015 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : BLACK |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| Defect | Result | Remarks | |
|--|--------|-----------------------------|-------------------------------|
| AUTOMATIC TEST: | | | |
| 13 Brake System | | | الفرامل |
| 13.04 - Brake Test | Passed | | فحص الفرامل |
| 14 Exhaust Gas Test | | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | | فحص الغاز العادم-الكربون |
| VISUAL TEST: | | | |
| 04 Tires Rims | | | الاطارات والعجلات |
| 04.01 - Front Left And Right Hands Tires | | ALL TYRES DOT 2015 & CRACKS | الاطارات الامامية |
| 04.07 - Rims | | SCRATCHES | الرنجات |
| 05 Body | | | الهيكل |
| 05.02 - Paint | | BODY SCRATCHES/ DENTS | الصبغ |
| 06 General Items | | | الاشياء العامة |
| 06.14 - Transmission Condition | | OK | حالة ناقل الحركة |
| 06.16 - Engine Condition, Smoke | | OK | حالة المحرك - الدخان |
| 07 Remarks | | | ملاحظات |
| 07.04 - Others | | 36145 KMS | ملاحظات اخرى |
| 09 Auction | | | الفحص الكامل |
| 09.06 - Chassis Ok | | | الشاصي جيد |
| 09.24 - Digital Display Damaged/Warning Lights | | TYRE PRESSURE LIGHT ON | عطل في لوحة التحكم الالكتروني |
| 09.25 - Body Repainted | | BODY PORTIONS REPAINTED | اثر صبغ في المركبة |

The Test Certificate Shows the test Result at the time of inspection only.