CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3012463
Transaction Date	20 Nov 2026, 14:07:31
Site Name	840 - Emirates Auctions
Transaction Number	20417699 (CC10013) (CC10011)



Vehicle Details

Chassis Number	KL1ZA5CS5N*******
Specification	GCC Specification
Make	Chevrolet
Model	Malibu
Model Year	2022
Color	White
Mileage	110249 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT LEFT SIDE REPAINTED REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE PORTION REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENT	الارضية
01.F Bumper	MINOR SCRATCHES	دعامية
01.G Trunk	REPAINTED PORTION REPAIRED,REFITTED	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED DIRTY CHCEK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Engine Visual Condition	MISFIRING , SHAKING , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	JERKING , MINOR OIL LEAK , PARTS GETTING RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2025,RIGHT WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	OK	المكيف
09.C Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH DAMAGED FROM MAIN PANEL	مفتاح النافذه و الزجاج
09.D Dash Board	PORTION LOOSE	لوحة القياده
09.E Door Panel	LEATHER PORTION LOOSE	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae