



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>21 Apr 2022, 13:05:42</b>
Transaction Number	<b>83071452 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WDD2229861A456613</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>S650 Maybach</b>
Model Year	<b>2019</b>
Color	<b>Black</b>
Mileage	<b>1553 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>European Imported</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Visual Gear Box Condition	OK	حالة الجير النظرى
02.B Road Test	NOT CHECK	فحص علي الطريق
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Paint	OK	الصبغ
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	OK	حالة المحرك النظرى
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.