CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2937387
Transaction Date	02 Nov 2026, 16:52:43
Site Name	840 - Emirates Auctions
Transaction Number	45043292 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JS3TD0D21J*******
Specification	GCC Specification
Make	Suzuki
Model	Grand Vitara
Model Year	2018
Color	Grey
Mileage	153218 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED,	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Bumper	MISALIGN	دعامية
01.E Bonnet	REPAINTED,PORTION REPAIRED	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY PORTION GETTING RUSTY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY MINOR SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2023 & RIGHT SIDE 2022	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR CONDITION RUSTY. SIGN OF FLOODED.	اخري
09.B Mirror	LEFT SIDE ADJUSTMENT NOT WORKING	المرايا
09.C AC Condition	OK	المكيف
09.D Power Window Switch And Glass	REAR LEFT SIDE NOT WORKING	مفتاح النافذه و الزجاج
09.E Door Panel	PORTION DAMAGED	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae