CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2915919
Transaction Date	27 Oct 2026, 15:59:12
Site Name	840 - Emirates Auctions
Transaction Number	41685094 (CC10013) (CC10019)



Vehicle Details

Chassis Number	MNTBB7A94K*******
Specification	GCC Specification
Make	Nissan
Model	Sentra
Model Year	2019
Color	White
Mileage	109512 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY TOTALY,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED DIRTY MUDDY	الارضية
01.E Bonnet	REFITTED	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED PORTION GETTING RUSTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Engine Visual Condition	MUDDY DIRTY PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOR JERKING , MUDDY , PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	MINOR LEAK	ممتص الصدمات
07.B Arms	ARM BUSHES DRY CRACK	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودات
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED & CENTER CONSOLE BOX COVER WORN OUT	اخري
09.B AC Condition	OK,REAR GRILL LOOSE	المكيف
10 Battery Condition		حالة البطارية
10.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae