CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2923729
Transaction Date	30 Oct 2026, 15:56:47
Site Name	840 - Emirates Auctions
Transaction Number	85844998 (CC10009) (CC10025)



Vehicle Details

Chassis Number	WBSKT6100F*******
Specification	GCC Specification
Make	BMW
Model	X5
Model Year	2015
Color	Grey
Mileage	85660 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT FIBER PAINT NOT CHECK	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR BOTH SIDE & FRONT RIGHT SIDE PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Sign of back accident	BACK PANEL DENT	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE ALL UNDER FLOOR CHASSIS COVERS FOR RECHECK PROPERLY	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OIL LEAK REFITTED	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT , BACK COVER DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY, OIL WET	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE BOX SLIDING COVER DAMAGED / INTERIOR PARTS GETTING RUSTY	اخري
08.B AC Condition	OK	المكيف
08.C Dash Board	LEATHER REPLACED PORTION LOOSE	لوحة القياده
08.D Door Panel	LEATHER PORTION LOOSE	لوحة بطانة الباب
08.E Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae