CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906107
Transaction Date	29 Oct 2026, 16:06:35
Site Name	840 - Emirates Auctions
Transaction Number	12950056 (CC10010) (CC10011)



Vehicle Details

Chassis Number	WDBWK45F09*******
Specification	GCC Specification
Make	Mercedes
Model	SLK 200
Model Year	2009
Color	White
Mileage	186544 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED,LOGO MISSING	دعامية
01.E Windshield	PORTION DAMAGED	زجاج
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION CRACK CUT,WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2024 CRACKED.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED WORN OUT	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES.	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CRACKED.	ربلة المقود
10.B Steering Box	OIL LEAK.	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CONSOLE BOX NOT OPEN	اخري
11.B AC Condition	NOT CHECK	المكيف
11.C Audio	ANTENNA MISSING	صوتيات
11.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.E Gear Shifting Lever	KNOB,DUST COVER WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae