



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>06 Sep 2022, 11:16:52</b>
Transaction Number	<b>71286842 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>MHKEF8BF8KK004623</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Rush</b>
Model Year	<b>2019</b>
Color	<b>White</b>
Mileage	<b>115007 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT RIGHT SIDE PORTION REPAIRED,REPAINTED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAIRED, REPAINTED,MINOR DENT,SCRATCHES	الصبغ
01.C Floor	UNDER FLOOR PARTS CHASSIS THICK RUST PROOFED	الارضية
01.D Trunk	PORTION REPAIRED,REPAINTED & REFITTED	صندوق
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	OK	المكيف
02.B Steering Wheel and control buttons	MINOR WORN OUT	عجلة القيادة وازرار التحكم
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	OK	حالة المحرك النظري
<b>05 Transmission Condition</b>		<b>الجير</b>

DEFECT	REMARKS	
05.A Visual Gear Box Condition	OK	حالة الجير النظري
05.B Road Test	NOT CHECK	فحص علي الطريق
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>07 Seats Condition</b>		<b>المقاعد</b>
07.A Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Ball Joint	BOOT CUT	مفصل كروي
<b>09 Chassis Condition</b>		<b>الشاصي</b>
09.A Chassis	OK/RUST PROOFED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.