



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>19 Jan 2023, 17:01:14</b>
Transaction Number	<b>37373866 (CC10010)</b>	Queue Number	<b>657683</b>



Chassis Number	<b>1FMEU73E19UA20298</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Ford</b>
Model	<b>Explorer</b>
Model Year	<b>2009</b>
Color	<b>--</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Odometer reading	NOT CHECK	قراءة عداد المسافات
01.B Mirror	REAR VIEW MIRROR FADED	المرآيا
01.C Roof Light	SUNGLASS CONSOLE BOX LOCK DAMAGED	أنارة السقف
01.D AC Condition	NOT CHECK	المكيف
01.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.F Dash Board	PORTION CRACKED	لوحة القيادة
01.G Door Panel	PORTION DAMAGED	لوحة بطانة الباب
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Visual Gear Box Condition	NOT CHECK,OIL LEAK REFITTED	حالة الجير النظري
02.B Road Test	NOT CHECK	فحص علي الطريق
<b>03 Steering Condition</b>		<b>المقود</b>
03.A Steering Oil	OIL LEAK	زيت المقود
03.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
03.C Axle	BOOT CUT	اكسلات

DEFECT	REMARKS	
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Rear Tyre	BOTH SIDE 2014 EXPIRED .CRACKED.	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2014 EXPIRED .CRACKED.	الاطار الامامي
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,OIL LEAK REFITTED	حالة المحرك النظري
<b>06 Body</b>		<b>جسم المركبة</b>
06.A Bonnet	CHROME MISSING	غطاء المحرك
06.B Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
06.C Vehicle Color	MAROON	لون المركبة
06.D Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES PORTION FADED	الصبغ
06.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Ball Joint	BOOT CUT	مفصل كروي
07.B Other	STABILIZER LINK BOOT CUT	اخرى
07.C Arms	LOWER ARM BUSH CRACKED	ازرع
07.D Shock Absorber	LEAK	ممتص الصدمات
<b>08 Seats Condition</b>		<b>المقاعد</b>
08.A Seat Condition	COVER DAMAGED	حالة المقاعد
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Head Light	LENS FADED,ALL LIGHT NOT CHECK,RIGHT SIDE PORTION DAMAGED	الاضاءة الرئيسية
<b>10 Chassis Condition</b>		<b>الشاسي</b>
10.A Chassis	CHASSIS FRAME RUSTY,OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.