CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2978008
Transaction Date	12 Nov 2026, 12:06:23
Site Name	840 - Emirates Auctions
Transaction Number	44567833 (CC10008) (CC10011)



Vehicle Details

Chassis Number	5XYPGDA56K*******
Specification	Imported
Make	Kia
Model	Sorento
Model Year	2019
Color	Black
Mileage	141882 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED REFITTED & REAR BOTH PORTION REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED,REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED ,PORTION GETTING RUSTY ,CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN PORTION CRACK	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED REFITTED,STAY SHOCK NOT WORKING	غطاء المحرك
01.H Pillars	RIGHT SIDE A/PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	REPAINTED PORTION REPAIRED,REFITTED	صندوق
01.J Sign of front accident		وجود مؤشر لحادث في المقدمة
01.K Sign of side accident		وجود مؤشر لحادث في الجانب
01.L Sign of back accident		وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION GETTING RUSTY COVERED CHECKED VISIBLE AREA / OK	الشاسيه
02.B Chassis Number	VIN CHECKED ON WINDSHILED ,LEFT SIDE STICKER ONLY	رقم القاعدة
03 Engine Condition		المحرك

Condition	Remarks	الحالة
03.A Engine Visual Condition	OIL LEAK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Belt	MIDDLE NOT WORKING	حزام الأمان
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS PORTION FADED	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACKED	الضوء الخلفي
07.C Warning Light	WARNING LIGHT SHOW ON DISPLAY	ضوء تحذير
08 Steering Condition		المقود
08.A Tie Rod End	RIGHT SIDE BOOT CUT ,LEFT SIDE MODIFIED	مؤخرة الرودات
09 Interior Condition		الحاله الداخليه
09.A AC Condition	OK,GRILL CHROME PANEL PORTION CRACK	المكيف
09.B Power Window Switch And Glass	GLASS FULL TINT	مفتاح النافذه و الزجاج
09.C FLoor Matting	EXTRA MATTING &VIN COVERED	فرش الأرضيه
09.D Dash Board	EXTRA COVER	لوحة القياده
09.E Roof Ceiling	PORTION DAMAGED WORN OUT	بطانه السقف
09.F Air Bag	RIGHT SIDE DAMAGED MISSING	وسائد هوائية
09.G Steering Wheel and control buttons	PORTION DAMAGED	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.