

Queue Number

2874183

Transaction Date

16 Oct 2026, 16:45:06

Site Name

840 - Emirates Auctions

Transaction Number

29871730 (CC10013) (CC10025)



Vehicle Details

Chassis Number	SALGS2SE3L*****
Specification	Imported
Make	Range Rover
Model	--
Model Year	2020
Color	Black
Mileage	88691 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED , LEFT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERED CHECK VISIBLE AREA ONLY	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Other	FRONT LEFT SIDE RUNNING BOARD AREA REPAIRED	اخرى
01.H Fuel Tank	DAMAGED	خزان الوقود
01.I Sign of front accident	FRONT ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.J Vehicle Model	HSE	طراز المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسية
02.B Other	FOR FULL INSPECTION MAKE WASH & REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	اخرى
02.C Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Other	UPPER COVER MISSING / INNER COMPARTMENT COVER PART MISSING	اخرى
------------	--	------

Condition	Remarks	الحالة
03.B Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		الاجير
04.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	LEFT SIDE 2025 , RIGHT SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	ازرع
07.B Other	SUSPENSION PARTS REFITTED	اخرى
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A AC Condition	OK	المكيف
08.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	CAP PORTION CRACK	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae